



CENTRAL MIDLANDS EQC DISTRICT
PO Box 156, Building #5
State Park, SC 29147

May 26, 1999

Wilson Mill Pond , Inc.
c/o Marion B. Hope
P.O. Box 5677
Columbia, SC 29250

RE: Reinspection of Dam D-0594, Wilson Millpond Dam, Richland County

Dear Mr. Hope:

On Tuesday, May 18, 1999, I conducted a routine reinspection of the above referenced dam.

I am enclosing a copy of the inspection report on the dam. Overall, the dam appears to be in **poor** condition. **(NOTE: Any deficiencies are listed on the inspection report)**

I have verified the telephone numbers on the Emergency Notification Plan and a copy is enclosed for your use. Should the dam experience difficulty, you should contact all of the numbers on the plan. The agencies listed on the plan can provide assistance in blocking roads and doing other things that need to be done in the event of an emergency.

Provisions in the SC Dams and Reservoirs Safety Act require the owner to notify us (SC DHEC) within thirty (30) days after transferring title or control of a dam to someone else. The notification must include the name, address and telephone number of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next reinspection of this dam is scheduled.

Sincerely,

Kendrick R. Chiles
Environmental Engineer Associate
Central Midlands EQC District Office

Enclosures

cc: Richard Yongue, DHEC Bureau of Water Facilities Compliance

INSPECTION REPORT

Date May 18, 1999

Dam D-0594, Wilson Millpond Dam

Representatives of SCDHEC Present: Kendrick R. Chiles

Representatives of Owner Present: None

Others Present: None

List of noted deficiencies or items requiring correction/checking:

* All vegetation (brush and weeds), all dead trees and limbs, and small trees (less than 6" in diameter) should be cut and removed from dam.

* Trees growing crest of dam should be removed.

* There are numerous holes and sinkholes on the crest of the dam. This problem should be addressed and corrected immediately.

* Trash and debris should be cleared from the spillway inlet.

* Slopes of dam were not able to be thoroughly inspected due to thick vegetation.

Note: Dam should remain clear of vegetation year round.

List of previously noted items still uncorrected and dates previously noted:

Emergency Action Plan Updated Yes _____ No x



Signature of Person Completing Form