


EXPLANATION

- ⊕ Approximate monitoring well location
- ⊞ Approximate recovery well location

Aerial Photograph Source: © Google; October, 2010.



C:\PROJECTS\01-29288\ASITE LAYOUT\COLUMBIA SC2.DWG



DRAFTED BY: \GMILES

DATE: 1/30/2012

Site Layout

SEACO, Inc.
2700 William H. Tuller Drive & 2701 Commerce Drive
Columbia, South Carolina

Figure
2