

FormEditor.txt

follow up visit on 7-6-15 to be sure the dam pool was still drained. Results-Dam was retaining water and was back to normal pool. Called owner and explained he must lower. Emailed dam program downtown to inform them of situation.

Lexington Mill Pond pictures July 7, 2015

Hauptmann, Steve E.

Mon 7/6/2015 3:33 PM

To: Poole, John <POOLEJA@dhec.sc.gov>; Milenkov, Petar <MILENKPI@dhec.sc.gov>;

📎 4 attachments (8 MB)

IMG_3761[1].JPG; IMG_3762[1].JPG; IMG_3767[1].JPG; IMG_3768[1].JPG;

John,

Laben said he did try to bring the level up a little on Thursday of last week to keep the fish from dying but that the rain caused it to go higher than he anticipated. I reminded him of the severity of the situation and the danger to the public. He made it clear that he understood and would not let this happen again.

Steven

Steven Hauptmann, Engineering EIT
SC Department of Health and Environmental Control
Midlands Region BEHS-Richland, Lexington, Fairfield, Newberry
Physical location: 8500 Farrow Road, Building 12, Columbia, SC 29203
Mailing address: P.O. Box 156, State Park, SC 29147-0156
email: hauptmse@dhec.sc.gov
803-896-9646 (office)
803-920-0786 (cell)
803-896-0617 (fax)