

What is a Registration Permit?

Registration Permits

[SC Regulation 61-62, Section II \(I\)](#), allows for the implementation of registration permits. Registration permits may be developed and implemented for specific source groups with uncontrolled [potential emissions](#) below the threshold for [major source](#) groups. Similarity in equipment and process remove the need for in depth site-specific review of each and every facility. All registration permits must contain the standard permit conditions listed in [SC Regulation 61-61.2, Section II\(J\)\(1\)](#), and can contain additional special conditions that ensure the source's compliance with any emission limitations and operational requirements. A source must meet the criteria specified the registration permit to qualify for a registration permit. If the source is later determined to not meet the criteria and terms of the registration permit, then the facility may be subject to enforcement.

Why use a registration permit for area sources?

Air pollutant emissions from many area sources are comparatively low and have not previously triggered SC air permitting requirements. Even though a single area source facility may have low air pollutant emissions, a large number of area source facilities in the same area can have harmful impacts to health and the environment. The area source standards developed by the EPA reduce that health and environmental impact. The registration permit is a good fit for many area sources because it will be a single document that contains all the requirements an area source facility will need to comply with their particular area source regulation. Registration permits are not meant for facilities that trigger multiple, complex permitting requirements that often require several types of air permits.

Area Source Standards

****Dry Cleaning Facilities***

Subpart M - National Perchloroethylene Air Emission Standards for Dry Cleaning Facilities

- [e-CFR for Area Source \(40 CFR 63\) Subpart M](#)

****Hospital Ethylene Oxide Sterilizers***

Subpart WWWW - National Emission Standards for Hospital Ethylene Oxide Sterilizers

- [EPA Brief Summary for Area Source \(40 CFR 63\) Subpart WWWW](#)
- [e-CFR for Area Source \(40 CFR 63\) Subpart WWWW](#)

****Iron and Steel Foundries***

Subpart ZZZZ - National Emission Standards for Hazardous Air Pollutants for Iron and Steel Foundries Area Sources

- [EPA Fact Sheet for Area Source \(40 CFR 63\) Subpart ZZZZ](#)
- [e-CFR for Area Source \(40 CFR 63\) Subpart ZZZZ](#)

****Gasoline Distribution Bulk Terminals, Bulk Plants, and Pipeline Facilities***

Subpart BBBBBB - National Emission Standards for Hazardous Air Pollutants for Source Category: Gasoline Distribution Bulk Terminals, Bulk Plants, and Pipeline Facilities

- [EPA Brief Summary for Area Source \(40 CFR 63\) Subpart BBBBBB](#)
- [e-CFR for Area Source \(40 CFR 63\) Subpart BBBBBB](#)

****Gasoline Dispensing Facilities***

Subpart CCCCCC - National Emission Standards for Hazardous Air Pollutants for Source Category: Gasoline Dispensing Facilities

- [EPA Brief Summary for Area Source \(40 CFR 63\) Subpart CCCCCC](#)
- [e-CFR for Area Source \(40 CFR 63\) Subpart CCCCCC](#)

****Polyvinyl Chloride and Copolymers Production Facilities***

Subpart DDDDDD - National Emission Standards for Hazardous Air Pollutants for Polyvinyl Chloride and Copolymers Production Area Sources

- [EPA Fact Sheet for Subpart DDDDDD](#)
- [e-CFR for Area Source Subpart DDDDDD \(Part 1\)](#)
- [e-CFR for Area Source Subpart DDDDDD \(Part 2\)](#)

****Paint Stripping and Miscellaneous Surface Coating Operations***

Subpart HHHHHH - National Emission Standards for Hazardous Air Pollutants: Paint Stripping and Miscellaneous Surface Coating Operations at Area Sources

- [EPA Brief Summary for Autobody Shops](#)
- [EPA Brief Summary for Miscellaneous Surface Coating](#)
- [EPA Brief Summary for Paint Stripping](#)
- [e-CFR for Area Source Subpart HHHHHH](#)

****Acrylic and Modacrylic Fibers Production Facilities***

Subpart LLLLLL - National Emission Standards for Hazardous Air Pollutants for Acrylic and Modacrylic Fibers Production Area Sources

- [EPA Fact Sheet for Area Source Subpart LLLLLL](#)
- [e-CFR for Area Source Subpart LLLLLL](#)

****Flexible Polyurethane Foam Production and Fabrication Facilities***

Subpart OOOOOO - National Emission Standards for Hazardous Air Pollutants for Flexible Polyurethane Foam Production and Fabrication Area Sources

- [EPA Brief Summary for Area Source Subpart OOOOOO](#)
- [e-CFR for Area Source Subpart OOOOOO](#)

****Lead Acid Battery Manufacturing Facilities***

Subpart PPPPPP - National Emission Standards for Hazardous Air Pollutants for Lead Acid Battery Manufacturing Area Sources

- [EPA Implementation Brochure for Area Source Subpart PPPPPP](#)
- [e-CFR for Area Source Subpart PPPPPP](#)

****Wood Preserving Facilities***

Subpart QQQQQQ - National Emission Standards for Hazardous Air Pollutants for Wood Preserving Area Sources

- [EPA Brief Summary for Area Source Subpart QQQQQQ](#)
- [e-CFR for Area Source Subpart QQQQQQ](#)

****Clay Ceramics Manufacturing Facilities***

Subpart RRRRRR - National Emission Standards for Hazardous Air Pollutants for Clay Ceramics Manufacturing Area Sources

- [EPA Implementation Brochure for Area Source Subpart RRRRRR](#)

- [e-CFR for Area Source Subpart RRRRRR](#)

****Secondary Nonferrous Metals Processing Facilities***

Subpart TTTTTT - National Emission Standards for Hazardous Air Pollutants for Secondary Nonferrous Metals Processing Area Sources

- [EPA Fact Sheet for Area Source Subpart TTTTTT](#)
- [e-CFR for Area Source Subpart TTTTTT](#)

****Plating and Polishing Operations***

Subpart WWWWWW - National Emission Standards for Hazardous Air Pollutants: Area Source Standards for Plating and Polishing Operations

- [EPA Brief Summary for Area Source Subpart WWWWWW](#)
- [e-CFR for Area Source Subpart WWWWWW](#)

****Nine Metal Fabrication and Finishing Source Operations***

Subpart XXXXXX - National Emission Standards for Hazardous Air Pollutants Area Source Standards for Nine Metal Fabrication and Finishing Source Categories

- [EPA Brief Summary for Area Source Subpart XXXXXX](#)
- [e-CFR for Area Source Subpart XXXXXX](#)

For the complete table listing the current Area Source Rules, [click here](#).

Contacts:

Elizabeth Basil
basilej@dhec.sc.gov
(803) 898-4126

Mary Peyton Wall
wallmp@dhec.sc.gov
(803) 898-4064