

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
Laurens County					
AM PM FOOD STORE	PETRO	UST	BLWM		Site ID # 10284. RBCA Classification 4AA8. Awaiting Funding.
BAILEY PROPERTY	PETRO	UST	BLWM		Site ID # 15325. RBCA Classification 4BC8. Awaiting Funding.
BLALOCK TEXTILE MILL	PETRO, VOC	UNK	BOW		Monitored natural attenuation.
BRAGG CONVENIENCE STORE	PETRO	UST	BLWM		Site ID # 15476. RBCA Classification 2BB8. Awaiting Funding.
BUCKS AUTO SALES	PETRO	UST	BLWM		Site ID # 09837. RBCA Classification 2AA4. Active corrective action.
CALDWELL SERVICE STATION	PETRO	UST	BLWM		Site ID # 11291. RBCA Classification 2BA1. Conducting investigation/Risk Assessment.
CAROLINA COMMERCIAL HEAT TREATING LLC	PETRO	UST	BLWM		Site ID # 05608. RBCA Classification 4AA5. Inactive.
CAROLINA GAS & GRILL	PETRO	UST	BLWM		Site ID # 05666. RBCA Classification 3BF5. Inactive.
CHILDRESS CASH & CARRY	PETRO	UST	BLWM		Site ID # 11279. RBCA Classification 3BA1. Conducting investigation/Risk Assessment.
CITY OF CLINTON C&D LANDFILL	VOC	LF	BLWM		In monitoring phase. Low level of vinyl chloride in MW-2A. Permit # 301002-1201.
CLINTON MILLS INC	VOC	LF	BLWM		In monitoring phase. Requested Appendix II sampling. VOC's in MW-2 and MW-3. Permit # 194200-1201, DWP-019.
CLINTON MILLS-PLANTS 1 AND 2	VOC, METALS	OTHER, UNK	BLWM	SCD980079479	BLWM File # 52085. In assessment and monitoring phases. Plume is discharging to creek/storm water network.
CLINTON TIRE SERVICE INC	PETRO	UST	BLWM		Site ID # 15629. RBCA Classification 4AA5. Inactive.
COMMUNITY QUICK SHOP	PETRO	UST	BLWM		Site ID # 11694. RBCA Classification 3BA1. Conducting investigation/Risk Assessment.
CONTINENTAL MACHINE CO	PETRO	UST	BLWM		Site ID # 15813. RBCA Classification 2BA8. Awaiting Funding.
COPELAND GULF	PETRO	UST	BLWM		Site ID # 05698. RBCA Classification 2BA8. Awaiting Funding.
COPELANDS SERVICE STATION INC	PETRO	UST	BLWM		Site ID # 05694. RBCA Classification 2BA8. Awaiting Funding.
CORNER STOP 55	PETRO	UST	BLWM		Site ID # 05700. RBCA Classification 3BA8. Awaiting Funding.
CORNER STOP 58	PETRO	UST	BLWM		Site ID # 10223. RBCA Classification 4BC1. Conducting investigation/Risk Assessment.
CRYOVAC DUMP SITE	METALS	LF	BLWM	SCD980844021	No activity at this time.
DEBS QUICK STOP	PETRO	UST	BLWM		Site ID # 15736. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaitei.

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
DELOACH GROCERY	PETRO	UST	BLWM		Site ID # 16096. RBCA Classification 3BD8. Awaiting Funding.
E Z SERVE 8170	PETRO	UST	BLWM		Site ID # 10496. RBCA Classification 3AA7. Approved Monitored Natural Attenuation (MNA Awaite).
ENMARK 160	PETRO	UST	BLWM		Site ID # 05669. RBCA Classification 3BA1. Conducting investigation/Risk Assessment.
ENMARK 310	PETRO	UST	BLWM		Site ID # 05664. RBCA Classification 3BA8. Awaiting Funding.
ERNESTINE STARNES PROPERTY	PETRO	UST	BLWM		Site ID # 15460. RBCA Classification 2BB8. Awaiting Funding.
FARMERS TEXACO	PETRO	UST	BLWM		Site ID # 11293. RBCA Classification 2BA7. Approved Monitored Natural Attenuation (MNA Awaite).
FORMER KING OIL FACILITY	PETRO	UST	BLWM		Site ID # 18888. RBCA Classification 5A7. Approved Monitored Natural Attenuation (MNA Awaite).
FREDS GULF BP	PETRO	UST	BLWM		Site ID # 14183. RBCA Classification 3BD3. Monitored Natural Attenuation.
FULLERS GULF	PETRO	UST	BLWM		Site ID # 05707. RBCA Classification 4AA8. Awaiting Funding.
GRAY COURT EXXON	PETRO	UST	BLWM		Site ID # 05701. RBCA Classification 3BA3. Monitored Natural Attenuation.
GREENWOOD MILLS COTTON INSULATION	PETRO	UST	BLWM		Site ID # 05697. RBCA Classification 5A7. Approved Monitored Natural Attenuation (MNA Awaite).
GURPREET ENTERPRISES INC	PETRO	UST	BLWM		Site ID # 11885. RBCA Classification 3BA8. Awaiting Funding.
H D PAYNE & COMPANY	PETRO	UST	BLWM		Site ID # 11256. RBCA Classification 3BF5. Inactive.
HIGHWAY 221 SOUTH	PETRO	UST	BLWM		Site ID # 11290. RBCA Classification 2BA4. Active corrective action.
HILL OIL CO	PETRO	UST	BLWM		Site ID # 05621. RBCA Classification 3BA1. Conducting investigation/Risk Assessment.
HOLLIDAY GROCERY	PETRO	UST	BLWM		Site ID # 11285. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
HOME STORE 1	PETRO	UST	BLWM		Site ID # 05702. RBCA Classification 3BA8. Awaiting Funding.
HWY 14 QUICK STOP	PETRO	UST	BLWM		Site ID # 17615. RBCA Classification 4BC1. Conducting investigation/Risk Assessment.
JIM & DONNAS TRADING POST	PETRO	UST	BLWM		Site ID # 18333. RBCA Classification 2BB8. Awaiting Funding.
JOE KELLYS TROPHY SHOP	PETRO	UST	BLWM		Site ID # 10292. RBCA Classification 2BB5. Inactive.
KMO 122	PETRO	UST	BLWM		Site ID # 10300. RBCA Classification 4AA8. Awaiting Funding.

LAURENS County
Groundwater Contamination Inventory
South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
LAURENS CERAMTEC	VOC	S/L	BOW		In remediation phase. Remediation options being evaluated for plant two area. Water well has been impacted. Contaminant discharging to an unnamed tributary and Reedy Fork.
LAURENS CNTY SCHOOL DIST 56-MARTHA DENDY 6TH GRDE CNTR	PETRO	UST	BLWM		Site ID # 10315. RBCA Classification 4AA8. Awaiting Funding.
LAURENS COMMISSION OF PUBLIC WORKS	PETRO	UST	BLWM		Site ID # 12847. RBCA Classification 5A5. Inactive.
LAURENS COUNTY MSW LANDFILL	VOC	LF	BLWM		In assessment phase. Plume is discharging to on-site unnamed tributary. Below MCL detection of one VOC (cis-1,2 Dichloroethene) in a grab sample from creek. Permit # 301001-1101.
LAURENS PATROL FACILITY	PETRO	UST	BLWM		Site ID # 05591. RBCA Classification 2BB5. Inactive.
LIL CRICKET 837	PETRO	UST	BLWM		Site ID # 05671. RBCA Classification 5A5. Inactive.
MICHELIN LAURENS PROVING GROUNDS	PETRO	UST	BLWM		Site ID # 05607. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
MOONS LANDING	PETRO	UST	BLWM		Site ID # 11276. RBCA Classification 2AA8. Awaiting Funding.
PIEDMONT PETROLEUM CORP	PETRO	UST	BLWM		Site ID # 05675. RBCA Classification 2BA4. Active corrective action.
QUICK FOOD MART 5	PETRO	UST	BLWM		Site ID # 05668. RBCA Classification 2BA8. Awaiting Funding.
QUICK POINT LAURENS	PETRO	UST	BLWM		Site ID # 10019. RBCA Classification 4AA7. Approved Monitored Natural Attenuation (MNA Awaiti.
RAMAGES TEXACO	PETRO	UST	BLWM		Site ID # 11264. RBCA Classification 3BF5. Inactive.
RANDY SIMS EXXON	PETRO	UST	BLWM		Site ID # 05663. RBCA Classification 2BB1. Conducting investigation/Risk Assessment.
RC PATEL LLC	PETRO	UST	BLWM		Site ID # 05712. RBCA Classification 4AA8. Awaiting Funding.
ROPER'S WEE SHOPPE	PETRO	UST	BLWM		Site ID # 15134. RBCA Classification 3BA5. Inactive.
RUBYS FOOD STORE	PETRO	UST	BLWM		Site ID # 05670. RBCA Classification 3BA5. Inactive.
SAV WAY 207	PETRO	UST	BLWM		Site ID # 12466. RBCA Classification 4AA5. Inactive.
SHOP N SAVE	PETRO	UST	BLWM		Site ID # 05713. RBCA Classification 4AA1. Conducting investigation/Risk Assessment.
SHORT STOP	PETRO	UST	BLWM		Site ID # 05678. RBCA Classification 3BA1. Conducting investigation/Risk Assessment.
SHORT STOP OF CLINTON INC	PETRO	UST	BLWM		Site ID # 18363. RBCA Classification 4AA5. Inactive.

LAURENS County
 Groundwater Contamination Inventory
 South Carolina - 2008

Contamination Incident	Type of Contaminant	Source of Contamination	Bureau	U.S. EPA ID	Remarks
SOUTHERN STORES 504	PETRO	UST	BLWM		Site ID # 11859. RBCA Classification 5A1. Conducting investigation/Risk Assessment.
SPEEDWAY 620	PETRO	UST	BLWM		Site ID # 05647. RBCA Classification 3BD7. Approved Monitored Natural Attenuation (MNA Awaits).
SPEEDY FOOD 1	PETRO	UST	BLWM		Site ID # 10375. RBCA Classification 4BC5. Inactive.
TIMKEN (FORMER TORRINGTON CLINTON BEARINGS PLANT)	VOC	UST, PPL	BLWM	SCD003345683	In assessment, monitoring, and remediation phases. Hazardous waste permit for post-closure care issued December 1996. Groundwater contamination off-site. Plant is closed.
WELBORNS FISHING SUPPLY	PETRO	UST	BLWM		Site ID # 13930. RBCA Classification 2BB7. Approved Monitored Natural Attenuation (MNA Awaits).
WILSON COUNTRY MARKET	PETRO	UST	BLWM		Site ID # 11259. RBCA Classification 3BF5. Inactive.
YOUNGS GULF STATION	PETRO	UST	BLWM		Site ID # 05695. RBCA Classification 4AA1. Conducting investigation/Risk Assessment.
Total for Laurens	69				